EXHIBIT 40



[stamp:] Ret. Rec. Req.

INTERNAL CORRESPONDENCE

RATION AND PRODUCTION
BURGOS FACILITY [A.I.B.]

167

SENDER:	NUMBER: 237-39100-39110-OF-498/ /2006 FILE: B-14-S.
Well Operation and Exploration Facilities Coordination Office Well Operation Department	DATE: June 5, 2006
DESTINATION:	BACKGROUND OF COMMUNICATION
Physical Security Management	WHICH IS ANSWERED WITH THIS
ATTENTION:	INSTRUMENT
Fermín González González	NUMBER:
	FILE(S):
	DATE(S):
SUBJECT:	APPENDIXES:
Access Anomaly Report Cañón 1A Station.	X

WHEN ANSWERING THIS OFFICIAL LETTER, MENTION THE AGENCY WHICH SENT IT AS WELL AS ITS AMOUNT AND DATE

I hereby inform you that on June 4 of the current year, the "E" Pumping Assistant Rolando Sosa Mozqueda F-477799, assigned to this Coordination Office, reported that at 08:10 a.m., he found that the access door chain of the Station mentioned in this matter was cut, an incident carried out by persons not related to our company and the door of the facility was open. The door was inspected detecting that the storage tank liquid level was in accordance with the well production rate in the Station, so that it is presumed that they tried to steal condensate.

Evidence was then taken and the chain was again ordered installed and the lock put in place. The worker's report and the photographs of the incident are attached.

All the above is for the purposes and effects that may apply.

Sincerely, [signature] Jorge Morales Cerón Coordinator.

[stamp:]
PHYSICAL SECURITY SERVICES MANAGEMENT
JUNE 8, 2006
PETROLEOS MEXICANOS
DEPT. REYNOSA, TAM.

CC: Well Operation Department

[initialed:] VC / JVCG / EVL / ES / laa

"2006, Year of the Bicentenary of the Birth of the Outstanding Patriot of the Americas, Sir Benito Juárez García"

PEP-0007591





FORM PEP CI-4

INTERNAL CORRESPONDENCE

Bertoob i neibii i	
SENDER:	NUMBER: 237-39100-39110-OF-159/ /2007
Well Operation and Exploration Facilities Coordination Office	FILE: B-14-S. 61
Well Operation Department	DATE: February 26, 2007
DESTINATION:	BACKGROUND OF COMMUNICATION WHICH IS
Physical Security Services Management, Dept. Reynosa, Tam. ATTENTION: José Pablo Rodríguez Mondragón	ANSWERED WITH THIS INSTRUMENT
	NUMBER(S) 237-39100-39110-OF-498/167/2006
	237-39100-39110-OF-530/180/2006
	237-39110-OF-581/2006
	FILE(S): B-14-S [stamp:] Ret. Rec. Req.
	DATE(S): June 5, June 12, and June 23, 2006
SUBJECT:	APPENDIXES:
Guard Services in A.I.B. Station	X

WHEN ANSWERING THIS OFFICIAL LETTER, MENTION THE AGENCY WHICH SENT IT AS WELL AS ITS AMOUNT AND DATE

For the purpose of maintaining the facilities in accordance with the guidelines of Petróleos Mexicanos security as well as the good performance of the activities and operations within the collection station Cañón 1 and 1A, I would be grateful if you would order the pertinent persons to carry out the permanent guard service, due to the fact that in this station, personnel unrelated to the company has been carrying out activities which result in serious contamination problems in the station and surrounding area, as is shown in the photographic evidence. Don't let me forget to mention that this type of actions have been happening as well in the Stations Topo 1, Sigma 1, Sigma 2, Fundador 1, Mojarreñas 1, Culebra 9, Peña Blanca 1, Arcabuz 3, Arcabuz 4, and Pípila 1, regarding which requests were made in the attached documents, but concerning which we have not received any response to date.

Sincerely,

[signature] Alejandro Valle Corona Interim Coordinator.

> [stamp:] PHYSICAL SECURITY SERVICES MANAGEMENT FEB. 28, 2007 PETROLEOS MEXICANOS DEPT. REYNOSA, TAM.

CC: **Burgos Facility**

> Quality, Env. Prot, and Indus. Security Coordination Office, A.I.B. Logistics and Maintenance Coordination Office

[initialed:] ECR / JGA / ESS / mce



FORM PEP CI-4

INTERNAL CORRESPONDENCE

20110	
SENDER:	NUMBER: 237-39100-39110-OF-212/ /2007
Well Operation and Exploration Facilities Coordination Office	FILE: B-14-S. 82
Well Operation Department	DATE: March 8, 2007 [stamp:] Ret. Rec. Req.
DESTINATION:	BACKGROUND OF COMMUNICATION WHICH IS
Physical Security Services Management, Dept. Reynosa, Tam.	ANSWERED WITH THIS INSTRUMENT NUMBER(S): 237-39100-39110-OF-159-61-2007
	FILE(S):
ATTENTION: José Pablo Rodríguez Mondragón	DATE(S): February 26, 2007
	· · · · · · · · · · · · · · · · · · ·
SUBJECT:	APPENDIXES:
Permanent Guard Services in the Facility	

WHEN ANSWERING THIS OFFICIAL LETTER, MENTION THE AGENCY WHICH SENT IT AS WELL AS ITS AMOUNT AND DATE.

In response to your communication GSSF/DSFR/305/2007 dated March 5, 2007, where you mention that you do not have the necessary means to cover the permanent guard service needs in the areas of our jurisdiction, we reiterate the request for continuous guard service, preferably at night, since we consider them as critical points due to the constant movement of staff unrelated to the company in the Collection Stations Cañón 1-A, Cañón 2, Sigma 1 and 2, Compression Station Sierrita-Cuervito, taking into account their list of staff and work hours.

Don't let me forget to mention that these actions cause considerable losses for the company, as well as serious contamination problems, not to mention that a bigger accident could be provoked.

Sincerely,

[signature]
Alejandro Valle Corona
Interim Coordinator.

CC: Quality, Env. Prot, and Indus. Security Coordination Office, A.I.B.

Logistics and Maintenance Coordination Office

[initialed:] ECR / lhc Received by me Jaime Juárez [signature]

03/12/2007 Guard Service Agent



INTERNAL CORRESPONDENCE

EXPLORATION AND PRODUCTION **BURGOS FACILITY**

SENDER:	NUMBER: 237-39100-39110-OF-159/ /2007
Well Operation and Exploration Facilities Coordination Office	FILE: B-14-S. 61
Well Operation Department	DATE: February 26, 2007
DESTINATION:	BACKGROUND OF COMMUNICATION WHICH IS
Physical Security Services Management, Dept. Reynosa, Tam. ATTENTION: José Pablo Rodríguez Mondragón	ANSWERED WITH THIS INSTRUMENT
	NUMBER(S): 237-39100-39110-OF-498/167/2006
	237-39100-39110-OF-530/180/2006
	237-39110-OF-581/2006
	FILE(S): B-14-S [stamp:] Ret Rec Req.
	DATE(S): June 5, June 12, and June 23, 2006
SUBJECT:	APPENDIXES:
Guard Services in A.I.B. Stations	X

WHEN ANSWERING THIS OFFICIAL LETTER, MENTION THE AGENCY WHICH SENT IT AS WELL AS ITS AMOUNT AND DATE.

Document 400-29

For the purpose of maintaining the facilities in accordance with the guidelines of Petróleos Mexicanos security as well as the good performance of the activities and operations within the collection station Cañón 1 and 1A, I would be grateful if you would order the pertinent persons to carry out the permanent guard service, due to the fact that in this station, personnel unrelated to the company has been carrying out activities which result in serious contamination problems in the station and surrounding area, as is shown in the photographic evidence. Don't let me forget to mention that this type of actions have been happening as well in the Stations Topo 1, Sigma 1, Sigma 2, Fundador 1, Mojarreñas 1, Culebra 9, Peña Blanca 1, Arcabuz 3, Arcabuz 4, and Pípila 1, regarding which

requests were made in the attached documents, but concerning which we have not received any response to date.

Sincerely,

[signature] Alejandro Valle Corona Interim Coordinator.

> [stamp:] PHYSICAL SECURITY SERVICES MANAGEMENT FEB. 28, 2007 PETROLEOS MEXICANOS DEPT. REYNOSA, TAM.

CC: **Burgos Facility**

Quality, Env. Prot. and Indus. Security Coordination Office, A.I.B.

Logistics and Maintenance Coordination Office

[initialed:] ECR / JGA / ESS / mce

List of Return Receipts

Page 1 of 1

LIST OF RETURN RECEIPTS OF THE DOCUMENT: 237-39100-39110-OF-212-82-2007

Name	or Agency	Ret. Rec.	Ret. Rec.	Delivery Date
	23711000BURGOS SIPAC COORDINATION OFFICE			
CCP	DELGADO AVILES MARCO ANTONIO			03/09/2007
	23716000BURGOS LOGISTICS AND MAIN. COORD.	1	03/09/2007	
OFFIC	E		07:21:47	
			p.m	
CCP	ZAMUDIO DIAZ JUAN MANUEL			03/09/2007

D=SENT TO, CCP=WITH COPY TO, T=TRANSFERRED TO, TCCP=GREEN SHIFT COPY TO AREA HEADS

http://sacv30.sede.dpep.pep.pemex.com/WebSAC3_0/Seguimiento/ListAcuses.aspx?nombreRef=2373... 03/13/2007



[stamp:] Ret. Rec. Req.

INTERNAL CORRESPONDENCE

EXPLORATION AND PRODUCTION **BURGOS FACILITY**

SENDER:	NUMBER: 237-39110-OF-270/2007
Well Operation Department	FILE: B-5-1-S.
	DATE: April 3, 2007.

DESTINATION: Pipelines and Facilities Maintenance Department	BACKGROUND OF COMMUNICATION WHICH IS ANSWERED WITH THIS INSTRUMENT NUMBER(S): [stamp:] PEMEX EXPLORATION AND PRODUCTION, APR 10, 2007,
ATTENTION: Jaime Rosendo Zubiaga Gaytán	RECEIVED, PIPELINES AND FACIL. MAINT. DEPT. FILE(S): DATE(S):
SUBJECT: Repair perimeter fence of Reynosa Sector Station	APPENDIXES:

WHEN ANSWERING THIS OFFICIAL LETTER, MENTION THE AGENCY WHICH SENT IT AS WELL AS ITS AMOUNT AND DATE.

As a result of illicit activities of the theft of condensate in different stations in the sector, personnel unrelated to our company have caused damages to the perimeter fence of the facilities, causing cattle to entered into the facilities.

In order to avoid the death of livestock for this reason, I hereby request the repair of the fencing in the following facilities:

- Pípila 1 Station.
- Sigma 2 Station.
- Lomitas 2 Station.
- Cañón 2 Station

Sincerely,

[signature] Alejandro Valle Corona Interim Coordinator.

Well Operation and Facilities Coordination Office cc: Quality, Env. Prot. and Indus. Security Coordination Office, A.I.B.

[initialed:] ECR / JVC / marh

List of Return Receipts

Page 1 of 1

LIST OF RETURN RECEIPTS OF THE DOCUMENT: 237-39100-OF-270-2007

Name or Agency		Ret. Rec.	Ret. Rec.	Delivery Date
	23711000BURGOS SIPAC COORDINATION OFFICE	1	04/09/2007 06:40:27	
			p.m.	
CCP	DELGADO AVILES MARCO ANTONIO			04/09/2007
	23711300SUSTAINABLE DEVELOPMENT AND			
QUAL	JTY			
T	MUÑOZ GONZÁLEZ GILDARDO			04/09/2007
	23739100COPY BURGOS	1	04/09/2007	
İ			02:40:24	
			p.m.	
CCP	MORALES CERON JORGE			04/09/2007
	23739110WELL AND FACILITIES OPERATIONS			
T	VALLE CORONA ALEJANDRO	1	04/10/2007	04/10/2007
			02:51:24	
			p.m.	
T	CASTILLO RODRÍGUEZ EDUARDO			04/11/2007
T	GUERRA ABAD JESÚS			04/11/2007
	23763400PIPELINES AND ACCESSES	1	04/10/2007	
MAINTENANCE			07:50:55	
			a.m.	
D	ZUBIAGA GAYTÁN JAIME ROSENDO			04/09/2007
T	DIAZ OLIVARES JESÚS ZARAGOZA			04/11/2007

D=SENT TO, CCP=WITH COPY TO, T=TRANSFERRED TO, TCCP=GREEN SHIFT COPY TO AREA HEADS

http://sacv30.sede.dpep.pep.pemex.com/WebSAC3_0/Seguimiento/ListAcuses.aspx?nombreRef=2373... 04/11/2007



2009, Year of the Liberal Reform

Official Letter

Date:

July 16, 2009

Sender: S.C.A.D.A.

Number:

COPIE-SCA-OI-083-2009

Wells Operation and Exploitation Facilities Coordination Office

Burgos Facility

Destination:

Jorge Javier Fernandez Garza

E.D. Patrimony and Services Administration, A.I.B.

Background: Number(s):

Unique File Number:

Date(s):

Attention:

Subject: Damage to solar panel in Culebra 2 Station

Appendix X

By means of this letter, allow me to inform you regarding the damages detected on July 15 of the current year in the

SCADA system monitoring equipment located in the Culebra 2 Station.

According to the informational note IMP/SCADA/HAGU-007-09, generated by the area SCADA supervisor, upon

making a routine inspection run of the instruments of said station, there are observed damages on the solar panel, brand name BP SOLAR, model BP 3805, serial no. C1061111 4996925.

It should be mentioned that no theft of this equipment has been detected.

The supervisor's informational note and the photographic evidence are appended.

Sincerely, [signature] José Ángel Escobedo Torres Int SCADA Leader, A.I.B.

CC:

José Aldaberto Ríos Espit.- Well Operation and Exploration Facilities Coordinator.

Jorge Luis Vivero Flores.- Legal Sub-Manager, Reynosa.

Marco Antonio Delgado Avilés. - Quality, Environmental Protection and Industrial Security Coordinator, A.I.B.

Pedro Hugo Robles Sosa.- Sectorial Head, Arcabuz-Culebra.

José Pablo Rodríguez Mondragón.- Physical Security Department Head.

File:

RJLR

S C.A.D.A. - Administrative Building No 1, 3rd Floor, Blvd. Lázaro Cárdenas No. 605, Colonia Anzalduas, Postal Code 88630, Ciudad Reynosa, Tam. Switchboard 921 76 00 Extensions 50330 and 50331

Page 1

PEP-0007598



INSTITUTO MEXICANO DE PETRÓLEO [Mexican Institute of Petroleum] NORTHERN AREA REGIONAL OFFICES

INNOVATE

IMP/SCADA-MAGU-007-09

DATE 07/15/2009

INFORMATIONAL NOTE

<u>FOR</u>: ENG. RUBÉN LÓPEZ ROBLES. SUPERVISOR OF THE SCADA A.I.B.

FROM: ENG. HUGO AUGUSTO GONZÁLEZ URBANO

SUBJECT: DAMAGES ON SOLAR PANEL IN CULEBRA 2 STATION.

I am hereby informing you that when carrying out the routine inspection run of the instruments of Culebra 2 station, damages were detected on the solar panel described below, and when connecting the electricity to the Remote Terminal Unit Master of the wireless system, it was found to be operating properly. In anticipation of lowered efficiency of the damaged solar panel during the winter season, we suggest that this equipment be changed.

Solar Panel brand name: BP Solar, Model: PB 3805, serial number: C1061111 4996925

Photographs appended.

With nothing further to consider, I remain available for inquiries.

Sincerely
[signature]
Eng. Hugo Augusto González Urbano
Supervisor, IMP/SCADA

CC: J.A.E.T./Leader SCADA


	BLVD MORELOS #990 2°	ENCINOS #507	1	CALLE MONTERREY #411 ALTO	OS .
	PISO, COL PROL	COL DEL VALLE C P		COL RODRIGUEZ C P 88630	
	RODRIGUEZ C P 85690	88620			
			ADMINISTRATION	ENGINEERING	EXPLORATION AND
	CONSULTANCY AND	EXPLORATION AND	TEL 824 53 37	TEL 926 35 57	PROD
	TRAINING OFFICE	PROD	EXT 52171	EXT 5 21 79	TECHNICAL SERVICES
	TEL 926 87 73	GEOPHYSICAL REG	1	E-MAIL rortegap@imp mx	TEL 23 95 07 EXT 32291
i	EXT 52176	TEL 925 15 43		0.0.	
		EXT 32064			


PEP-0007599



INSTITUTO MEXICANO DE PETRÓLEO [Mexican Institute of Petroleum] NORTHERN AREA REGIONAL OFFICES

INNOVATE





BLVD, MORELOS #990 2° PISO, COL. PROL. RODRIGUEZ C.P. 85690

> CONSULTANCY AND TRAINING OFFICE TEL. 926 87 73 EXT. 52176

ENCINOS #507 COL. DEL VALLE C.P. 88620

EXPLORATION AND PROD. GEOPHYSICAL REG. TEL. 925 15 43 EXT. 32064

CALLE MONTERREY #411 ALTOS COL. RODRIGUEZ C.P. 88630

ADMINISTRATION TEL. 824 53 37 EXT. 52171


ENGINEERING TEL. 926 35 57 EXT. 5 21 79 E-MAIL: rortegap@imp.mx


EXPLORATION AND PROD. TECHNICAL SERVICES TEL. 23 95 07 EXT. 32291



INSTITUTO MEXICANO DE PETRÓLEO [Mexican Institute of Petroleum] NORTHERN AREA REGIONAL OFFICES

INNOVATE





BLVD MORELOS #990 2° PISO COL PROL RODRIGUEZ C P 85690

CONSULTANCY AND TRAINING OFFICE TEL 926 87 73 EXT 52176 ENCINOS #507 COL DEL VALLE C P 88620

EXPLORATION AND PROD GEOPHYSICAL REG TEL 925 15 43 EXT 32064 CALLE MONTERREY #411 ALTOS COL RODRIGUEZ C P 88630

ADMINISTRATION
TEL 824 53 37
EXT 52171

ENGINEERING TEL 926 35 57 EXT 5 21 79 E MAIL rortegap@imp mx EXPLORATION AND PROD TECHNICAL SERVICES TEL 23 95 07 EXT 32291



Informational Note

Date

Reynosa, Tamps, July 22, 2009

From:

Eddy Alberto González Guillén (3464)

Eduardo Joaquín Castillo Mañón (4393) Phys. Security Dept. Agents, Revnosa

For:

Jorge Herrera López **Operations Coordinator** Phys. Security Dept., Reynosa

ATTENTION

Subject: Tanker truck theft in the vicinity of the Fronterizo 2 collection station.

Document 400-29

We are hereby informing you that today (July 22, 2009), at approx. 12:30, during our patrol of the production fields of the Burgos Facility of PEMEX Exploration and Production, we detected an abandoned tanker truck in the vicinity of the Fronterizo 2 collection station, located in the municipality of General Brayo, Nuevo León, coordinates 25° 50' 30" north latitude and 098° 50' 51" west longitude.

The characteristics of the tanker truck are stated as follows:

Tractor Trailer brand name Freightliner color red, with unit number 170 without license plates, with logotype on the driver's door of the CTM [Confederation of Mexican Workers] and the words "Private Use, National Union of Transportation and Construction Workers in general and similarly related organizations of the Mexican Republic, CTM, Aldama No. 625-D, Colonia Centro, Reynosa, Tamps.," hitched to the gray-colored tank, with no visible brand name, with two axles, with unit number 394 and 4064, license plates 332-4GK from the State of Oklahoma, United States, with an approximate capacity of 30 thousand liters, full to 70% of capacity with a hydrocarbon product which appears to be field condensate.

We proceeded to take the corresponding samples, which were then transferred to the PEP laboratory to subject them to physical chemical analysis, which generated as a result that they have the characteristics of the field condensate produced by Pemex Exploration and Production.

Likewise, we are letting you know that, due to security measures, the seized tanker truck was transferred to the Facility designated Culebra Sur Plant of Pemex Exploration and Production, located in the "El Huizache" cooperative in the Municipality of General Bravo, Nuevo León.

All the above was made known to the Legal Sub-Manager of Pemex in Reynosa, for the corresponding legal handling.

We make this known to you for the corresponding purposes and effects.

[signature] Eddy Alberto González Guillén (3454)

Sincerely, [signature] Eduardo Joaquín Castillo Mañón (4393)

Page 1

[stamp:] RETURN RECEIPT REQUESTED

Official Letter

Date:

Number

Reynosa, Tamps., July 29, 2009

DSFR-0962-2009

Sender:

Destination:

Administration Corporate Office.

Physical Security Services Management

Reynosa, Tamp. Department

Mr. Jorge Luis Vivero Flores

Reynosa Legal Sub-Manager

Reynosa, Tam.

Background:

Number(s):

Unique file number:

Date(s):

Subject: Intervention of 1 subject and tanker truck with field condensate.

Appendix:

X

REDACTED

Sincerely, [signature] Jorge Herrera López Operations Coordinator

> [stamp:] PHYSICAL SECURITY SERVICES MANAGEMENT JULY 29, 2009 PETRÓLEOS MEXICANOS REYNOSA, TAM. DEP..

[stamp:] [illegible] July 29, 2009, RECEIVED [stamp:] GENERAL OFFICE OF THE LAWYER

PEMEX PETRÓLEOS MEXICANOS JULY 29, 2009 05:10 P.M. RECEIVED REYNOSA LEGAL OFFICE

Cc: General of [illegible], Organización Editorial Mexicana, Ret. Miguel Estrada Martínez, Physical Security Services Manager, Mexico, D.F., for their full knowledge.

Cc: Eng Miguel Ángel Maciel Torres, Administrator of the Burgos Facility of PEP. Cc: File

Prepared by JHL

Page 1

PEP-0007603

PETRÓLEOS MEXICANOS PHYSICAL SECURITY SERVICES MANAGEMENT

REYNOSA DEPARTMENT

Reynosa, Tamps., July 29, 2009.

Subject: Informational report and presentation of a person

Citizen Agent of the Public Prosecutor's Office on duty Attention

The Citizens Genaro Cruz Martínez and Eduardo Joaquín Castillo Mañón, Agents of the Physical Security Services Department of Petróleos Mexicanos, assigned to the Reynosa Department, identified by their respective credentials numbers 3494 and 4393 issued by the state company, with domicile at Carretera Reynosa-Nuevo Laredo Km. 8.5 Ejido Los Cavazos in Reynosa, Tamps., bring to your attention the following events:

At approximately 03:45 a.m. today, the operator of the SCADA Control Room of the Burgos Facility of Pemex Exploration and Production, reported that at 3:27 a.m. there was noted the beginning of a decrease in the liquids in the Sigma 2 Station, such that yours truly, the undersigned, went out to carry out a patrol in the cited production field, noticing that a tanker truck was coming out of the secondary road which leads to that station, beginning to travel along the Carretera Monterrey-Reynosa, the tanker truck stopped at about 04:50 a.m. approximately at kilometer 190+800 of that highway, in the vicinity of the Santa Rosa Ranch, Municipality of Reynosa, Tamps., so that we proceeded to stop, detecting that it was driven by a subject who stated he was Erick Jaziel Castañeda Morales and that he was 27 years of age, with domicile at Calle Leyes de Reforma 114, Colonia Lázaro Cárdenas, of Reynosa, Tamps., such that it is presumed that this unit was filled in the Sigma 2 Station in light of the fact that in that place, a decrease was recorded in the SCADA Control Room.

As follows the characteristics of the tanker truck:

<u>Tractor Trailer</u> brand name Freightliner color red, with license plates <u>466-BP4</u> of the Mexico Federal Public Shipping Service, with serial number on the door frame <u>1FUYDCEB1VL823239</u>, with the company name JCB (Javier Cantu Barragán), Tel. 92-62-400, 92-62-401 and 95-42-400, Reynosa, Tamps., hitched to the white -colored <u>tank</u>, with a red strip all along the side, brand name Hercules, with no company name, serial number <u>3M9T140831H009318</u>, with no license plates, and three axles and an approximate capacity of 43 thousand liters, being it then observed that it was full to 95% of its capacity with a hydrocarbon product.

We proceeded to take the respective sample, which was then transferred to the PEP laboratory to subject it to physical chemical analysis, which generated as a result that it has the characteristics of the field condensate produced by Pemex Exploration and Production.

All the above was made known to the Legal Sub-Manager of Pemex in Reynosa.

For security measures and via instructions of the legal holder of power of attorney of this Company, the tanker truck will be transferred to the facility designated Campo Reynosa of Pemex Exploration and Production, located at Carretera San Fernando-Reynosa Km. 110+800 in the Colonia Pedro J. Méndez of this City, likewise, photographs were taken in the place where the tanker truck was intercepted.

Given the statements above and the instructions of the Legal Sub-Management of Pemex in Reynosa, in these offices we hereby make available to this investigatory authority the person who stated he is Erick Jaziel Castañeda Morales and that he is 17 years old, with domicile at Calle Leyes de Reforma 114, Colonia Lázaro Cárdenas in Reynosa, Tamps.

The person brought to the offices of this Honorable Social Agency of the Federation, exhibits no visible injury, has not been hit or mistreated, such that he is delivered in good physical and health conditions, and in this proceeding, we request that the medical certification of his physical integrity be to performed on him, likewise, we request that all the necessary procedures be performed which are deemed relevant by this agency under your honorable responsibility in order to clarify these events.

Sincerely,
The apprehending agents of the of Physical Security Services Management of Petróleos Mexicanos

[signature]
Genaro Cruz Martínez
(3494)

[signature] Eduardo Joaquín Castillo Mañón (4393)



EXPLORATION AND PRODUCTION

Official Letter

CLASSIFICATION Total b Partial
Reserved Confidential

Pages 72 Date January 2, 2009 Reserve Period 12 years

Legal Basis LFTAIPG [Federal Law of Transparency and Access to Official Public Information]

Articles 13 and 14, Sections I and IV I, III, IV, and VI

Others Political Constitution of United States of Mexico, Article 28 Fourth Paragraph National Security Law, Articles 5, Section XII, 51, Section II

General Guidelines of Classified and Declassified Information of Agencies and Entities

of the Federal Public Administration No 18, Section V, Point 'e" 25th

Extension of reserve period years

Part or section to be classified

Administrative Unit Well Op and Exp Facility Coordinating Office Name, position, and signature of the head of the Administrative Unit

Fernando Martinez Ballesteros, Department of Operations of Wells, Me

DECLASSIFICATION

Name, position, and signature of the head of the Administrative Unit

DATE: August 12, 2009

Sender: Administration of the Burgos Facility

Wells Operation and Exp. Fac.

Coordination Office

Well Operation Department

Number: AAIB-COPIE-DOP-480-

747-2009

Destination:

Juan Arturo Hernández Carrera

Northern Region Branch

Background:

Number(s):

Unique file number: 4S.7 File on Physical Security

Date(s):

Subject: Report on Physical Security, July 2009

Appendix:

X

Following up on our previous reports in this matter, referring to the theft of liquid hydrocarbons and equipment from the production facilities, I hereby append and send the report of the patrols performed by the Physical Security Management posted in Reynosa, Tamaulipas, which mentions two incidents related to acts of illegal transportation of condensates, a report of the missing volume (shrinkages), and three cases of incidents related to acts of theft of equipment.

Likewise, an informational note is attached, regarding the placing of chains and locks on the access to the facilities and spigots of the tanker trucks with a respective coverage of 100% and 97% as of August 11 of the current year.

Given all the above, we reiterate our request for your support before the corresponding authorities so they attend these matters.

I appreciate in advance your consideration of this matter and use this occasion to send you a cordial greeting.

Sincerely, [signature] Miguel Ángel Maciel Torres Administrator

Prepared by Fernando Martinez Ballesteros

SIPAC Regional Management - Carlos Hernandez Garcia Burgos Management Control - Ismael Nuñez Fernández [initialed] [illegible] DSC/MENE

"2009, Year of the Liberal Reform" Administration of the Burgos Facility Blvd Acapulco y Tamaulipas No 1901, Col Ampliacion Rodríguez, Reynosa, Tam, CP 88630 [text cut off]

PEP-0007606

PEMEX		"2009, Year of the Liberal Reform"	
EXPLORATION AND PRODUCTION ®		Official Letter Date: August 11, 2009	
	Arturo Hernández Carrera Manager of the Northern Region	Number: AAIB-COPIE-502009	
Destination:	Miguel A. Maciel Torres Administrator of the Burgos Facility	Background: Number(s): Unique file number: Date(s):	
Subject: Instal	llation of chains and locks on accesses of the A.I.B.	Appendix X	

In hereby inform you that based on the instructions, chains with locks have been installed on all the accesses to the stations of the Burgos Facility in accordance with the attached listing, as well as 97% coverage on the rapid fill control valves of the storage tanks, it is worth mentioning that as of this date, no violations of the locks or broken chains have been detected in the operational areas, if any irregularity is observed, we will so notify you in a timely fashion.

MAM/AVS [initials]

Exploration Facilities and Operations Coordination Office, Burgos Facility
Blvd Lazaro Cardenas No 605, Colonia Anzalduas, C P 88630, Telmex - 899 909045 Switchboard - 899 9217600 Ext 50450 Ciudad Reynosa, Tam

Page 1

PEP-0007607

PEMEX	"2009, Year of the Liberal Reform"		
EXPLORATION AND PRODUCTION ®	Shipment		
	Date: August 24, 2009		
Sender: Department of Operation of Wells Measurement of Gas and Liquids	Number: DOP-MGI-169-2009		
Destination: Juan González Ávila Contract Operations Coordination Office	Appendix		

For the purpose of continuing the control of the transportation of condensate in the stations under your responsibility, via this letter we are hereby sending 400 security seals to be utilized in the shipments of condensate in tankers by the companies under your responsibility in accordance with the attached dispatch voucher.

Sincerely, [signature] Alejandro Valle Corona Reynosa-Cuitláhuac Sectorial Head

[stamp:] **PEMEX**

EXPLORATION AND PRODUCTION

REYNOSA AUGUST 26, 2009 RECEIVED

CONTRACT OPERATIONS COORDINATION OFFICE

[initials] MEHE/cacc

Department of Operation of Wells Measurement of Gas and Liquids Blvd. Morelos Esq. Blvd. Tamaulipas s/n, Puerta No. 5 Col. Anzalduas, Reynosa, Tam., C.P. 88630, Switchboard (899) 9217600, Ext. 5-30-29

Page 1

PEP-0007608



DISPATCH VOUCHER FOR SEALS

DATE August 24, 2009

ENG. JUAN GONZÁLEZ **Contract Operations Management**

I did so receive the amount of:

400 SEALS WITH THE FOLLOWING NUMERATION:

FROM 002201 TO 002300 yellow FROM 002301 TO 002400 yellow FROM 002501 TO 002600 yellow FROM 002901 TO 003000 yellow

TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

[signature] [signature]

Received as per agreed upon Mario E. Hayashi Echeverría F-205426 Liquids Handling Section

> [stamp:] **PEMEX EXPLORATION AND PRODUCTION REYNOSA** AUGUST 26, 2009

RECEIVED CONTRACT OPERATIONS COORDINATION OFFICE

PEP-0007609



DISPATCH VOUCHER FOR SEALS

DATE August 24, 2009

ENG. FRANCISCO MAGDALENO LICON Coordination Office of Transportation and Distribution of Hydrocarbons

I did so receive the amount of:

100 SEALS WITH THE FOLLOWING NUMERATION:

FROM 002001 TO 002100 yellow

TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

[signature] [signature]

Francisco M. Licon F.243369

Mario E. Hayashi Echeverría F-205426 Liquids Handling Section

PEP-0007610



DISPATCH VOUCHER FOR SEALS

DATE August 27, 2009

ENG. FRANCISCO MAGDALENO LICON

Coordination Office of Transportation and Distribution of Hydrocarbons

I did so receive the amount of:

92 SEALS WITH THE FOLLOWING NUMERATION:

TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

[signature] [signature]

Received as per agreed upon

Mario E. Hayashi Echeverría F-205426 Liquids Handling Section

PEP-0007611

EXPLORATION AND

PEMEX EXPLORATION AND PRODUCTION WELL OPERATION AND EXPLORATION FACILITIES DEPARTMENT

DISPATCH VOUCHER FOR SEALS

DATE August 27, 2009

ENG. PEDRO H. ROBLES S. SECTOR ARCABUZ-CULEBRA-CUERVITO

I did so receive the amount of:

800 SEALS WITH THE FOLLOWING NUMERATION:

FROM 4801 TO 4900 blue FROM 4401 TO 4500 blue FROM 4001 TO 4100 blue FROM 3001 TO 3100 blue FROM 4301 TO 4400 blue

[4301 TO 4400 blue TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

FROM 4601 TO 4700 blue FROM 4901 TO 5000 blue FROM 4101 TO 4200 blue

[signature]

Eng. Rurico Hernández R. F.331114

Mario E. Hayashi Echeverría F-205426

Liquids Handling Section

[signature]

PEP-0007612



DISPATCH VOUCHER FOR SEALS

DATE August 27, 2009

ENG. ARIEL VALENZUELA SECTOR LAREDO

I did so receive the amount of:

400 SEALS WITH THE FOLLOWING NUMERATION:

FROM 3201 TO 3300 blue FROM 3101 TO 3200 blue FROM 3401 TO 3500 blue FROM 3601 TO 3700 blue

TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

[signature]

[signature]

Eng. Ariel Valenzuela.

Mario E. Hayashi Echeverría F-205426 Liquids Handling Section

PEP-0007613



DISPATCH VOUCHER FOR SEALS

DATE August 27, 2009

ENG. ALEJANDRO VALLE CORONA SECTOR REYNOSA

I did so receive the amount of:

500 SEALS WITH THE FOLLOWING NUMERATION:

FROM 3301 TO 3400 blue FROM 3901 TO 4000 blue

FROM 4501 TO 4600 blue

TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

FROM 4701 TO 4800 blue FROM 3801 TO 3900 blue

[signature] [signature]

Eng. Alejandro Valle Corona

Mario E. Hayashi Echeverría F-205426 Liquids Handling Section

PEP-0007614



EXPLORATION AND

DISPATCH VOUCHER FOR SEALS

DATE August 27, 2009

ENG. JUAN GONZÁLEZ Contract Operations Management

I did so receive the amount of:

400 SEALS WITH THE FOLLOWING NUMERATION:

FROM 12701 TO 12800 green FROM 12901 TO 13000 green FROM 11801 TO 11900 green FROM 12501 TO 12600 green

TO BE UTILIZED IN THE SHIPMENTS OF CONDENSATE IN TANKER TRUCKS

[signature] [signature]

Received as per agreed upon

Mario E. Hayashi Echeverría F-205426 Liquids Handling Section

[stamp:] WELLS OPERATION AND EXPLOITATION FACILITIES COORDINATION OFFICE **PEMEX** EXPLORATION AND PRODUCTION A.I.B. 10:00 a.m. AUGUST 27, 2009 [signature] **RECEIVED** GOPE BLOCKS SECTOR

PEP-0007615



CORRESPONDENCIA INTERNA

EXPLORACION Y PRODUCCION ACTIVO INTEGRAL BURGOS	167
REMITE:	NUMERO 237-39100-39110-OF -498/ /2006
Coordinación Operación de Pozos e Instalaciones de Explotación	EXPEDIENTE: BURL B.14-5.
Departamento de Operación de Pozos	FECHA 05 de Junio del 2006
DESTINO	ANTECEDENTES DE LA COMUNICACIÓN QUE SE
Gerencia de Seguridad Física ^{ATENCIÓN·} Fermín González González	CONTESTAN CON LA PRESENTE NUMERO- EXPEDIENTE(S): FECHA(S)
ASUNTO-	ANEXOS.
Reporte anomalia acceso Estación Cañón 1A.	×

OMZAV JEIG AVEJST Y CHEMANN JE CHOOD KOA JOHO Ó JEING ALDHEIGHEIGED AS EKENTÍO ÓKORO ETTE HATRIETHOGT.

Informo a usted que el día 04 de Junio del presente, el Ayudante "E" de Bombeo Rolando Sosa Mozqueda F- 477799, adscrito a esta Coordinación, reportó que a las 08:10 hrs. encontró la cadena de la puerta de acceso de la Estación citada en el asunto, cortada, hecho realizado por personas ajenas a nuestra empresa y la puerta de la instalación abierta. Se revisó la misma detectando que el nivel de líquidos de los tanques de almacenamiento estaban acorde al ritmo de producción de los pozos de la Estación, por lo que se presume intentaron robar condensado.

Se procedió a tomar evidencia y se mandó instalar nuevamente la cadena y colocar candado. Se anexan reporte del trabajador y fotografías del incidente.

Lo anterior para los fines que hayan lugar.

Atentamen

Jorge Morales Cerón Cooldinador

C c p Departamento de Operación de Pozos

GERENCIA DE SERVICIOS DE SEGURIDAD FISICA

8 2005

OPTO, REYNOSA, TAM

"2006, Ano del Bicentenario del natalicio del Benemerito de las Américas, Don Benito Juárez Garcia" المدار المدايلية الريخيش موالا عليد

FORMA PEP CI-4



CORRESPONDENCIA INTERNA

EXPLORACION Y PRODUCCION ACTIVO INTEGRAL BURGOS

REMITE:	NUMERO: 237-39100- 39110-OF-1592007			
Coordinación de Operación de Pozos e Instalaciones de Explotación.	EXPEDIENTE: B - 14- S 61			
Departamento de Operación de Pozos,	FECHA: 26 de Febrero de 2007			
DESTINO:	ANTECEDENTES DE LA COMUNICACIÓN QUE SE CONTESTA			
	CON LA PRESENTE			
Gerencia de Servicios de Seguridad Física, Depto. Reynosa, Tam.	NUMERO(S): 237-39100-39110-QF-498/167/2006 237-39110-39110-QF-530/180/2006 237-39110-QF-581/2006			
	EXPEDIENTE(S): B-14-S			
ATENCIÓN: José Pablo Rodríguez Mondragón	FECHA(S): 5 de Junio, 12 de Junio y 23-Junio de 2006			
ASUNTO:	ANEXOS:			
	x			
Vigilancia en Estaciones del A.I.B.				

AL CONTESTAR ESTE OFICIO CITESE LA DEPENDENCIA QUE LO GIRO. ASI COMO EL NUMERO Y FECHA DEL MISMO

Con la finalidad de mantener las instalaciones acorde a los lineamientos de seguridad de Petróleos Mexicanos así como el buen desempeño de las actividades y operaciones dentro de la estación de recolección Cañón 1 y 1A, agradeceré a usted ordenar a quien corresponda la vigilancia permanente, debido a que en dicha estación personal ajeno a la empresa ha estado realizando actividades que terminan en problemas serios de contaminación de la estación y área aledaña, tal como se muestra en la evidencia fotográfica.

No omito mencionar que este tipo de acciones se ha venido presentando también en las estaciones Topo 1, Sigma 1, Sigma 2, Fundador 1, Mojarreñas 1, Culebra 9, Peña Blanca 1, Arcabuz 3, Arcabuz 4 y Pípila 1, de lo cual se efectuaron solicitudes en documentos anexos, sin que hayamos recibido respuesta alguna hasta la fecha.

Atentamente,

Alejandro Valle Corona Ceordinador Interino.

C.c p.-Administración Activo Integral Burgos Coordinación Seg. Ind. Protecc. Amb. y Cahdad, A.I.B. Coordinación de Mantenimiento y Logistica FEB 28 2000
PETROLEOS MEXICANOS
DOTO, REYMOSA, TAM

FORMA PER CHA



CORRESPONDENCIA INTERNA

EXPLORACION Y PRODUCCION **ACTIVO INTEGRAL BURGOS**

ASUNTO:

REMITE: Coordinación de Operación de Pozos e Instalaciones de Explotación, A.I.B. Departamento de Operación de Pozos

NUMERO: 237-39100-39110-OF-212-

EXPEDIENTE: B-14-S

FECHA: 08 de Marzo de 2007

DESTINO: Gerencia de Servicios de Seguridad Física, Depto. Revnosa, Tam. ATENCIÓN: José Pablo Rodríguez Mondragón

ANTECEDENTES DE LA COMUNICACIÓN QUE SE **CONTESTAN CON LA PRESENTE**

NUMERO: 237-39100-39110-OF-159-61-2007 EXPEDIENTE(S):

FECHA(S 26 de Febrero de 2007

ANEXOS:

Vigilancia Permanente en Instalación

AL CONTESTAR ESTE UNICIO CÍTEIX. LA DEPENDENCIA QUE LO CIRCI ASICOMO EL MUMERO Y FECHA DEL MISMO

En atención a su comunicado GSSF/DSFR/305/2007 de fecha 05 de Marzo de 2007, donde nos comenta que no cuenta con los medios necesarios para cubrir la necesidad de vigilancia permanente en áreas de nuestra competencia, le reiteramos solicitud de vigilancia continua, preferentemente de noche, ya que consideramos puntos críticos por el constante movimiento de personal ajeno a la empresa en las Estaciones de Recolección Cañón 1-A, Cañón 2, Sigma 1 y 2, Estación de Compresión Sierrita - Cuervito, tomando en cuenta su planilla de personal y jornada de trabajo.

No omito mencionar que estas acciones le generan perdidas considerables a la empresa, además de problemas serios de contaminación, sin contar que pudiera provocarse un accidente mayor.

Atentamente,

Alejandro Valle Corona Coordinador Interino

C.c.p. Coord. Seguridad Industrial, Protección Ambiental y Calidad

Coord, Mantenimiento y Logística.

Recibir Jame Transferts
12-03-07. Agente dell Guardia



FORMA PEP CIJ

CORRESPONDENCIA INTERNA

EXPLORACION Y PRODUCCION ACTIVO INTEGRAL BURGOS

REMITE: Coordinación de Operación de Pozos e Instalaciones

de Explotación. Departamento de Operación de Pozos.

DESTINO:

Gerencia de Servicios de Seguridad Física, Depto. Reynosa, Tam.

ATENCIÓN: José Pablo Rodríguez Mondragón

ligilancia en Estaciones del A.I.B.

NUMERO: 237-39100- 39110-OF-159-

-2007

EXPEDIENTE: B - 14-S

61

FECHA: 26 de Febrero de 2007

ANTECEDENTES DE LA COMUNICACIÓN QUE SE CONTES CON LA PRESENTE

NUMERO(S): 237-39100-39110-OF-498/167/2006 237-39110-39110-OF-530/180/2006 237-39110-OF-581/2006

EXPEDIENTE(S): B-14-S

FECHA(S): 5 de Junio, 12 de Junio y 23-Junio de 2006

X

AL COMTESTAR ESTE OFICIO CÍTESE LA DEPENDENCIA QUE LO CRIO, ASI COMO EL MAMERO Y FECHA DEL MISMO

Con la finalidad de mantener las instalaciones acorde a los fineamientos de seguridad de Petróleos Mexicanos así como el buen desempeño de las actividades y operaciones dentro de la estación de recolección Cañón 1 y 1A, agradeceré a usted ordenar a quien corresponda la vigilancia permanente, debido a que en dicha estación personal ajeno a la empresa ha estado realizando actividades que terminan en problemas serios de contaminación de la estación y área aledaña, tal como se muestra en la evidencia fotográfica.

No omito mencionar que este tipo de acciones se ha venido presentando también en las estaciones Culebra 9, Peña Blanca d. Arcabuz 3, Culebra 9, Peña Blanca d. Arcabuz 3, Arcabuz 4 y Pípila 1, de lo cual se efectuaron solicitudes en documentos anexos, sin que hayamos recibido respuesta alguna hasta la fecha. 3. 9

Atentamente,

Alejandro Valle Corona Coordinador Interino.

C.c.p.-Administración Activo Integral Burgos Coordinación Seg. Ind. Protecc. Amb. y Calidad, A.I.B. Coordinación de Mantenimiento y Logistica

Lista de Acuses

Página 1 de 1

LISTA DE ACUSES DEL DOCUMENTO: 237-39100-39110-OF-212-82-2007

	Nombre o Dependencia		Fecha Acuse	FechaEntrega
	2371 1000COORDINACION DE SIPAC BURGOS			,
ССР	DELGADO AVILES MARCO ANTONIO			09/03/2007
	23716000COORD. MANTTO. Y LOGISTICA BURGOS		09/03/2007 07:21:47 p.m.	
CCP	ZAMUDIO DIAZ JUAN MANUEL	M		09/03/2007

D= DIRIGIDO A, GCP= CON COPIA PARA, T= TURNADO A, TCCP= COPIA DE TURNO EN VERDE JEFES DE AREA

http://sacv30.sedc.dpcp.pep.pemex.com/WebSAC3_0/Seguimiento/ListAcuses.aspx?nombrcRef=237-3... 13/03/2007



A / RCORRESPONDENCIA INTERNA

EXPL	ORA	CION	YPR	ODUC	CION
Δ.	CTIVE	INTE	CRAI	RURGO	25

REMITE:	NUMERO: 237-39110-OF-270/2007
Departamento de Operación de Pozos	EXPEDIENTE: B- 5-1-S
	FECHA: 03 de abril de 2007on
DESTINO:	ANTECEDENTES DE LA COMUNICACION QUE SEO
Departamento Mantenimiento a Ductos e Instalaciones	ANTECEDENTES DE LA COMUNICACIÓN QUE SEO CONTESTAN CON LA PRESENTE NUMERO: EXPEDIENTE(S):
Atención: Jaime Rosendo Zubiaga Gaytán	FECHA(S): 1 0 ABR 2007
ASUNTO:	ANEXOS:
Reparar cerca perimetral Estación Sector Reynos:	MANTO ADUCTOR

AL CONTESTAR ESTE OFICIO CÍTESE LA DEPENDENCIA DAE LO GIRO, ASÍ COMO EL MANERO Y FECHA DEL MISMO

Derivado de la actividad ificita de robo de condensado en las diferentes estaciones del sector, personal ajeno a nuestra empresa ha ocasionado daños a la cerca perimetral de las instalaciones, ocasionando que el ganado se introduzca en ellas.

Para evitar la muerte de semovientes por este motivo, solícito reparar el cercado de las siguientes instalaciones:

- Estación Pípila 1.
- Estación Sigma 2.
- · Estación Lomitas 2.
- Estación Cañón 2.

Atentamente,

Alejandro Valle Corolia Jefe_Depto. Operación de Pozos

C.c.p.Coordinación de Operación de Pozos e Instalaciones Coordinación de Seguridad Industrial, Protección Ambiental y Calidad

Página 1 de 1

LISTA DE ACUSES DEL DOCUMENTO: 237-39110-OF-270-2007

	Nombre o Dependencia		Acuse	Fecha Acuse	FechaEntrega
		23711000COORDINACION DE SIPAC BURGOS	V	09/04/2007 06:40:27 p.m.	
 	CCP	DELGADO AVILES MARCO ANTONIO			09/04/2007
	23711300DESARROLLO SUSTENTABLE Y CALYDAD				
	T	MUÑOZ GONZALEZ GILDARDO			09/04/2007
	23739100—COPIE BURGOS		✓	09/04/2007 02:40:24 p.m.	
	ССР	MORALES CERON JORGE			09/04/2007
	23739110 OPERACIÓN DE POZOS E INSTALACIONES				
معور معور	т	VALLE CORONA ALEJANDRO	√	10/04/2007 02:51:24 p.m.	10/04/2007
₹^	ŗ	CASTILLO RODRIGUEZ EDUARDO			11/04/2007
	т	GUERRA ABAD JESUS			11/04/2007
	23763400MANTENIMIENTO A DUCTOS Y VIAS DE ACESO		✓	10/04/2007 07:50:55 a.m.	
	b	2UBIAGA GAYTAN JAIME ROSENDO			09/04/2007
	Ť	DIAZ OLIVARES JESUS ZARAGOZA	8 2		11/04/2007

D= DIRIGIDO A, CCP= CON COPIA PARA, T= TURNADO A, TCCP= COPIA DE TURNO **EN VERDE JEFES DE AREA**

http://sacv30.sede.dpcp.pep.pemex.com/WebSAC3_0/Seguimiento/ListAcuses.aspx?nombreRef=237-3... 11/04/2007

2009, Año de la Ratorma Liberal



Oficio

16 de julo del 2009 Fedia COPIE-SCA-01-083-2009 Numero Remiunic SCADA. Coordinación de Operación de Pozos e Instalaciones de Explotación, Activo Integral Burgos Cestinatano Antecedentes Jorge Javier Fernández Garza Nún ero (a) E. D. Administración Patrimonial y Servicios, A.I.B. shreibagae ub ound oremund Fecha(s) Presente: Asunto: X Daño a panel spler en Estación Culebra 2 Anexo

Por medio del presente me permito informar a Usted, respecto a la alectación detectada el día 15de julio del presente año en el equipo de monitoreo del sistema SCADA ubicado en Estación Culebra 2.

De acuordo a nota informativa IMP/SCADA/HAGU-007-09 generada por supervisor SCADA del área, se observa al realizarse recorrido de rutina para revisión de instrumentos en dicha estación daño en panel solar moa, BP SOLAR, mod BP 3805, n/s: C1061111 4996925.

Cahe mencionar que no se detecto ninguna sustracción a dicho equipo.

Se anexa nota informativa de supervisor y evidencia fotográfica

Alentame/ite

Jose Ángel Ascobedo Torres Lider Int. del SCADA A.I B

C.u. r Jose Adalecto Rios Espai - Coord de Operación de Pozos e Institute Exploitación
Jorge Luis Vivero Flores - Subgenerie Juridico Reynosa
Marco Antomo Del_{grado} Avilles - Coord Reguntand Industria: Protección Amborital y Culinad A LB
Pedro Hugo Robles Sosa - Jele Sector Arcabuz - Culebra
Jose Pablo Rodriguez Mandragon - Jele Depto de Segundad Fisica

Arc avo

RJLR

Pagina 1



INSTITUTO MEXICANO DEL PETROLEO DIRECCIÓN REGIONAL ZONA NORTE

... IMP/SCADA-HAGU-007-09

PECHA: 15/07/2009

NOTA INFORMATIVA

<u>PARA</u>: ING. RUBEN LOPEZ ROBLES. SUPERVISOR DEL SCADA A.LB.

<u>de:</u> ing. hugo augusto gonzalez trhano

ASUNTO: DAÑO EN PANEL SOLAR DE ESTACION CULTURA 2.

Informo a usted que al realizarse recorrido de rutina para revisión de Instrumentos en la estación Culebra 2, se detecto daño en panel solar abajo descrito y al revisarse el suministro electrico a UTR maestra dal sistema inalámbrico, se encontró trabajando en forma adecuada. Previendo una baja eficiencia del panel solar dañado en época invernal se sugiere realizar cambio de este equipo.

on the officer of wearings of Tights

Panel Solar marca: bp solar, modelo: BP 3805, numero de serie: C1061111 4996925

Se anexan fotografías.

Sin otro particular guedo a sus órdenes.

Alantamente

Ing. Hugo Augusto González Urbano Supervisor IMP/SCADA

C.c.p. J.A.E.T./ Lider SCADA

. "

VD. MORELOS #9902", PISO

COL PROL RODRIGUEZ C.P. ABBDD

GONSULTORIA Y CAPACITACION TEL. 926 67.73 EXT. 5X176 ENCINOS #507 COL DEL VALUE (C.P. 88620


EXPLORACION Y PROD. REG GEORISICOS TEL 925 15 43 EXT. 32064 ADMINISTRAC


ADMINISTRACION TEL 1024 53 37 EXT. 52171 CALLE MONTERREY #411 ALTOS COL. RODRIGUEZ C.P. 58630

INGENIERIA TEL. 526 55 57 EXT. 5 21 76 E-MAIL (Orlegopolimo mx EXPLORACION Y PROD. SERVICIOS TECNICOS TEL. 23 95 07 ENT. 12291



INSTITUTO MEXICANO DEL PETROLEO







LIVO MUHELOS Y880 7 P 60 COL PROL RODRIGUEZ O F 88800


> DONEULTORIA Y CAPACITACION TEL 996 57 73 LXI 82178

ENGINOS #507 COL DEL VALLE C P 08020


EXPLORACION Y PROD REG GEOFISICOS TEL 923 15 40 EXT 22554


ADMINISTRACION TEL 024 53 37 EXT 52171 CALLE MONTERREY #411 AL FOS COL RODRIBUEZ C P 88038

INGENIERIA TEL 025 65 57 EXT 4: 21 79 E-MAIL writegap@mp.mx EXPLOPACION Y PROD SERVICIOS TECHICOS TEL 23 86 07 E/T 32201



INSTITUTO MEXICANO DEL PETROLEO DIRECCIÓN REGIONAL ZONA NORTE







VD. MORELOS #890 2º. PISO L. PROL RODRIGUEZ C.P. 88890


> CONSULTORIA Y CAPACITACION TEL. 926 57 73 EXT 52176

ENCINOS #507 COL DEL VALLE C.P. 88828

EXPLORACION YPROD. REG GEOFISICOS TEL 925 16 42 EXT. 32004

ADMINISTRACION TEL. 924 50:37 EDIT. 52171 COL RODRIGUEZ C.P. 88830

INGENIERIA TEL 926-05-57 EXT, 5:21-75 E-MAIL tottopan@imp.mx EXPLORACION Y PROD. SERVICIOS TECNICOS TEL, 23 00 07 EXT. 32291



Nota Informativa

Fecha

Reynosa, Tamps., a 22 de Julio de 2009

Ďe

.a.5

....

Eddy Alberto González Guillen (3454) Eduardo Joaquín Casillio Mañón (4393) Agenles de Seg. Fis. Depto. Reynosa

Para

Jorge Herrera López, Coordinador de Opéracionos, Departamento Seg Fis. Reynosa. PRESENTE

Acunio

, intervención de 1 autotampe a inmediaciones de esteción de recolocción Fronteriza 2.

Informamos à Usted que noy (22 Jul-09) siendo las 12:30 hrs. aprox., durante nuestro patrullaje en los campos productores, del Activo Integral Burgos de Pemex Exploración y Producción, detectamos un autotanque abandonado a inmediaciones de la estación de recolección Fronterizo 2, ubicada en el municiplo de General Bravo, Nuevo León, coordenadas 25º 60! 30° latitud norte y 098º 50' 51" longitud oeste:

Las características del autotanque son las que a continuación se indican:

Tractocamión marca Freightliner color rojo, con no. eco. 170 sin placas de circulación, con logotipo en la puerla del conductor de la CTM y la teyenda "Servicio Particular, Sindicato nacional de trabajadores de transporte y la construcción en gral. similares y conexas de la Republica Mexicana CTM, Aldama No. 625-D col. Cerritro Reynosa Tamps.", enganchado al tonel color Gris, no se le aprecia marca, de 2 ejes, con no. económico 394 y 4064, placas de circulación 332-4GK del estado de Oklahoma, EE.UU., con capacidad aproximada para 30 mil litros, lleno al 70% de su capacidad de producto hidrocarburo al parecer condensado de campo.

Se procedió a la toma de muestras correspondientes, mismas que fueron trasladadas al taboratorio de PEP para su análisis físico químico, arrojando como resultado que presentan características a condensado de campo que produce Pemex Exploración y Producción.

De igual forma, hacemos de su conocimiento que por medidas de seguridad, el autotanque asegurado fue trasladado a la instalación denominada Planta Culebra Sur de Pemex Exploración y Producción, ubicada en el ejido "El Huizache", Municipio de General Bravo, Nuevo León.

Lo anterior se hizo del conocimiento de la Subgerencia Jurídica de Pemex en Reynosa, para el encauzamiento legal correspondiente.

Lo que hacemos de su conocimiento para los fines y efectos correspondientes

Eddy Alberto Conzález Guillen (3454) Atentamente.

Eduardo Joaquín Castillo Mañón

(4393)

Pàgina 1





Oficio

		Foche	Rey rosa Tam, a 29 de Julio do	2009
Remitente	Direccion Corporativa de Administracion Gerencia de Servicios de Seguridad Física Departamento Reynosa, Tam	Mutuhto	DSFR-0982 2004	,
Deslinalano	Lic Jorge Luis Vivero Flores, Subgerente Jundico Reynosa Reynosa, Tam	Aniecedenies Num. 1/5) Numero unico da o Fechals	expodente	

REDACTED

Atentamente dorge berrete Copez Coordinador de Operaciones GERENCIA DE SERVICIOS DE SEGURIDAD FISICA

JUL 29 2009

PETROLEOS MEXICANOS

DPFG REYNOSA, TAM

Cicip Gial de Grita DEN Rei Migre-i Estuara Marina. Gerente de Servicios de Seguridad e isica. Méxica, D. E. pare se superior conocimiento. Cicip Ing. Migreti / ngel Majus - orres. Administra for del Activo Integral Bu 9 % de PEP.
Cicip ExpMin

Elubora JHL

Pàg na 1

PETROLEOS MEXICANOS GERENCIA DE SERVICIOS DE SEGURIDAD FISICA DEPARTAMENTO REYNOSA

Reynosa, Tamps a 29 de Julio de 2009

Asunto Parte informativo y puesta a disposicion de una persona

C Agente del Ministerio Público do la Federación en turno Presente

Los' CC Genaro Cruz Martinez y Eduardo Joaquin Castillo Mañon, Agentes de la Gerencia de Servicios de Seguridad Física de Petroleos Mexicanos, adscritos al Departamento Reynosa, identificados respectivamente con las credenciales número 3494 y 4393 expedidas por la paraestatal, con domicilio en carretera Reynosa-Nuevo Laredo kir 8 5 Ejido I os Cavazos en Reynosa, Tamps , hacemos de su conocimiento los siguientes hechos

Siendo aproximadamente fas 03 45 hrs del día de hoy, el operador del Cuarto de Control Scada del Activo Integral Burgos de Pemex, Exploración y Producción, reportó que a las 03 27 hrs sa registro el inicio de un decremento de líquidos en estación Sigma 2, por lo que los sucritos nos trasladamos a realizar patrullaje en el citado cámpo productor, percatandonos que un autotanque salía de la brecha que conduce a dicha estación, iniciando su desplazamiento sobre la carretera Monterrey-Reynosa, "mismo que detuvo su marcha siendo aproximadamente las 04 50 hrs a la altura aproximada del km 190+800 de dicha carretera, a inmediaciones del rancho Santa Rosa, Municipio de Reynosa, Tamps, por lo que procedimos a detonernos, detectando que era conducido por quien manifesto llamarse Erick Jaziel Castañeda Morales y contar con 27 años de edad con domicilio en calle Leyes de Reforma 114, Col Lazaro Cardenas de Reynosa Tamps, por lo que se presume que dicha unidad fue cargada en la estación Sigma 2 toda vez que er ese lugar se presonto el decremento registrado en el cuarto de control Scada

Las características del autotanque son las siguientes

Tractocamion marca Freightliner color rojo, con placas de circulación 466-BP4 del Servicio Publico Federal de Carga Mexico, con numero de serie en el marco de la puerta 1FUYDCEB1VL823239, con razón social JCB (Javier Cantu Barragan) Tel 92-62-400 92 62-401 y 95-42-400 Reynosa Tamps, enganchado al Tonel color blanco con fianja roja a lo largo marca Hércules sin razon social, numero de serie 3M9T140831H909318, sin placas circulación, de 3 ejes con capacidad aproximada para 43 mil litros, observandose lleno al 95% de su capacidad con producto hidrocarburo

Se procedio a la toma de una muestra respectiva, misma que fue trasladada al laboratorio de PEP para su analis s fisico quimico, arrojando como resultado que presentan características a condensado de campo que produce Pemex Exploración y Producción

Lo anterior se hizo del conocimiento de la Subgerencia Juridica de Pemex en Reynosa

Por medidas de segundad y poi indicación del apoderado legal de este Empresa el autotanque sera trasladado a la instalación denominada Campo Reynosa de Pemex Exploración y Producción, ubicada en carretera San Fernando-Reynosa km 110+800 de la colonia Pedro J. Mendez de esta Ciudad, de igual forma se tomaron fotografias en el lugar que fue intervenido el autotanque

Por lo expresado y por instrucciones de la Subgerencía Juridica de Pemex en Reynosa, en el interior de estas oficinas ponemos a disposición de esta autoridad investigadora a la persona que manifesto liamarse Erick Jazie Castañeda Morales y con ar con 27 años de edad, con domicilio en calle Leyes de Reforma 114, Col Lazaro Cardenas de Reynosa Tamps,

La persona puesta a su disposicion, en el interior de las oficinas de esta H Representación Social de la Federación, no presenta lesion visible no ha sido golpeado o maltratado, por lo que se entrega en buenas condiciones físicas de salud, y en este acto solicitamos se le practique la certificación medica de integridad física, de igual forma solicitamos que se realicen todas las diligencias necesarias que considere pertinentes esa representación a su digno cargo para el esclareormiento de los presentes hechos

Atentamente

agentes-aprehonsoros de la OSSF de Petroleos-Mexicanos

Genaro Cruz Martinez (3494)

Eduardo Joaquin Castillo Mañon (4393)

JEPLORAL	DEMEX DON Y PRODUCTION E	Oficio 	Pàginas: Fecha. Fundamento legal Ampliación del perío	Oiro(s):	Articuto: 13 y 14 Const. Pol E.U Ley Seg Nac. / Lin. Grales, Cla Admón Púb Fo	p.de Reserva: Frección, I y IV; (I.M. Art. 28 cuario Art. 5 Frecc XII Ar self, y Desciasif. In ed. 18" Frecc. V ir	parrato t. 51 Fracc. II ni. Dep. y Ent.
			Parle o sección a da Unidad Administrativi Inabia, carpa y rebica dal Famando Martinez B Medición da Gas y Li	sifican a. auto ceta Ui allesteros,	Coord. (ndad Adminsvativa	Opin, de Pazas e	
			DESCLASIFICACIÓ Páginas Numbe, cargo y mitra a di		a;	ech .	
•	·		Fecha	12 de a	goslo de 2009		
Remilente	Administración del Activo Integral Burgos Coordinación de Operación de Pozos e Inst. de Exp. Departamento de Operación de Pozos		Numero	AAJB-C	OPIE-D@P:480-	Title To Server	2009
Dostinatario	Juan Arturo Hernández Ca Subdirección Región Norte		Antecedentes: Número(s): Número único de expe Fecha(s):	diente.	45.7 Expediente	sabre la Seguna	ad Fisica

Dando continuidad a nuestros similares anteriores, referentes a la sustracción ilicita de hidrocarburos líquidos y equipos de instalaciones de producción, anexo envio informe de patrullajes efectuados por la Gerencia de Seguridad Física destacado en Reynosa Tamaulipas, el cual refiere dos incidemes relacionados con actos de transporte ilícito de condensado, un informe de volumen faltante (mermas) y tres casos de incidentes relacionados con actos de sustracción de equipo

Asimismo, se anexa nota informativa, sobre la colocación de cadenas y candados en acceso a instalaciones y tomas de autoranques con un complimiento de 100% y 97% respectivamente al 11 de agosto del año en curso.

Por to anterior, reitero nuestra solicitud de su apoyo ante las autoridades correspondientes para la atención a estos hechos.

Agradezco de antemano su aterición y aprovecho para enviarle un cordial saludo

Informe de Seguridad Física julio 2009

Asunia:

Aler

Elaboró

Fernando Madlagz Ballesteros

Gerancia Regional SIPAC.- Carlos Homándoz Garcia Control de Gestión Burgos.- Ismael Nuñez Fernandez

> "2009, Año de la Relorma Liberal" Administración del Activo Integral Burgos Blvd. Acaputco y Tamaulipas No. 1901, Col Ampliación Rodríguez, Reynosa, Tam., C.P.88630

F1 12 18 35 35 8 18



"2009, Año de la Reforma Liberal"

Oficio

		· ·	Fecha	11 de Agosto do 2009	L Drivit Tallian
Remitente	Juan Arturo Hernández Carrera Subdirector de la Región Norte	٠,	Número	AAIB-COPIE- 50-	- 2009
Destinatario	Miguel A. Maciel Torreş Administrador del Activo Integral Burgos	Antecedentes: Número(s): Número único de expediente: Fecha(s):			
Asunto:	Instalación de cadenas y candados a accesos de Instalaciones del A.I.B.	,	Anexo 🗵		

Informo a usted que en base la las instrucciones, se han instalado cadenas con candados a todos los accesos de las estaciones del Activo Integral Burgos de acuerdo a la relación anexa, así como un 97% de avance a las válvulas de control de carga rápida de los tanques de almacenamiento, cabe mencionar que a la focha no se ha detectado ningún candado violado o cadena rota en los sectores operativos, de presentarse alguna irregularidad se notificara con oportunidad.



12000 Año de la Reforma Libera



Remision

Remitente Departamento de Operación de Pozos Medición de Gas y Líquidos Destruatario Anexo

Juan Gonzalez Avila

Coordinación de Operación de Contratos

Cor la finalidad de continuar con el control en el transporte de condensado en las estaciones a su cargo, con la presente enviamos 400 sellos de seguridad para ser útilizados en los embarques de condensado en pipas por las compañías a su cargo de acuerdo al vale de salida que se anexa

Atentamente,

Alejnnoro Valle Corona Jefo Sector-Reynosh-Cuidéhdas

EXPLORACION Y PRODUCCION REPARCA

2 6 AGO. 2009

ADORDINACION DE OPERACION

//// MEHE/cacc'

> Departamento Operación de Pozos Medición de Gas y Enquidos Bixid Morelou Esq. Fivo Tamaulipas s/n. Puerta No. 5 Col. Anzelduas, Reynosa, Tam. C.P. 86630, Conn. (899) 9217600, Ext. 5.30-29

> > Pagina 1



VALE DE SALIDA DE SELLOS

FECHA 24-Agosto-09

ING. JUAN GONZALEZ

Gerencia de Operación de Contratos

cibi la cantidad de :

400 SELLOS CON LA SIGUIENTE NUMERACION

DEL 002201 AL 002300 color amarillo

DEL 002301 AL 002400 color amanlio

DEL 002501 AL 002600 color amarillo

DEL 002901 AL 003000 color amarillo

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN PIPAS

Recibiço orpoldad Mario E /hayashi Echevérria F-205425

Sección Manajo de Líquidos



2 6 AGO, 2009

COORDINACION DE OPERACION

VALE DE SALIDA DE SELLOS

FECHA 24-Agosto-09

ING. FRANCISCO MAGDALENO LICON

Coordinacion de transporte y Distribucion de Hidrocarburos

Francisco M. Ucon F.243369

cibi la cantidad de:

100 SELLOS CON LA SIGUIENTE NUMERACION

DEL 002001 AL 002100 color amarillo

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN PIPAS

VALE DE SALIDA DE SELLOS

FECHA 27-Agosto-09

ING. FRANCISCO MAGDALENO LICON

Recibido de Conformidad

CTDH

Recibi la cantidad de :

92 SELLOS CON LA SIGUIENTE NUMERACION

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN PIPAS

Mario E. hayashi Echeverna F-205426



í

PEMEX EXPLORACION Y PRODUCCION DEPARTAMENTO DE OPERACIÓN DE POZO E INSTALACIONES DE EXPLORACION

VALE DE SALIDA DE SELLOS

FECHA 27-Agosto-09

ING. PEDRO H. ROBLES S. SECTOR ARCABUZ-CULEBRA-CUERVITO

Recibi la cantidad de :

800 SELLOS CON LA SIGUIENTE NUMERACION

žL 4601 AL 4900 color azul

DEL 4401 AL 4500 color azul

DEL 4001 AL 4100 color azul

DEL 3001 AL 3100 color azul DEL 4301 AL 4400 color azul

DEL 4601 AL 4700 color azul

DEL 4901 AL 5000 color azul DEL 4101 AL 4200 color azul

Ing Rurico Hernandez R. F.331114

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN PIPAS

Mario E. hayashi Echeverria F-205426



VALE DE SALIDA DE SELLOS

FECHA 27-Agosto-09

ING. ARIEL VALENZUELA SECTOR LAREDO

Recibi la cantidad de :

400 SELLOS CON LA SIGUIENTE NUMERACION

£L 3201 AL 3300 color azul DEL 3101 AL 3200 color azul DEL 3401 AL3500 color azul DEL 3601 AL 3700 color azul

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN PIPAS

Ing. Ariel Valenzuela.

Mario E. hayashi Echeverria F-205426



VALE DE SALIDA DE SELLOS

FECHA 27-Agosto-09

ING. ALEJADRO VALLE CORONA SECTOR REYNOSA

Recibi la cantidad de :

500 SELLOS CON LA SIGUIENTE NUMERACION

.EL 3301 AL 3400 color azul DEL 3901 AL 4000 color azul DEL 4501 AL 4600 color azul DEL 4701 AL 4800 color azul DEL 3801 AL 3900 color azul

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN PIPAS

Ing. Alejandro Valle Corona

Mario E. hayashi Echeverna F-205426



VALE DE SALIDA DE SELLOS

FECHA 27-Agosto-09

ING. JUAN GONZALEZ

Gerencia de Operación de Contratos

Recibi la cantidad de :

400 SELLOS CON LA SIGUIENTE NUMERACION

DLL 12701 AL 12800 color verde DEL 12901 AL 13000 color verde DEL 11801 AL 11900 color verde DEL 12501 AL 12600 color verde

PARA SER UTILIZADOS EN LOS EMBARQUES DE CONDENSADO EN FIPAS

Recibido de Conformidad

Mario E. hayashi Echeverria F-205426





THE STATE OF NEW YORK

COUNTY OF NEW YORK

AFFIDAVIT OF TRANSLATION

Before me, the undersigned Notary appears who, after being first duly sworn, deposes and says that the facts contained herein are true and correct and based upon his personal knowledge:

- 1. "My name is Sara Hutchison. I am over the age of twenty-one years and competent to make this affidavit.
- 2. I am a project manager at TransPerfect Translations International Inc.
- 3. I am employed by TransPerfect Translations International Inc.
- 4. I hereby certify that the document attached hereto is "PEP-0007591-7615
- 5. I further certify that said translation is to the best of my knowledge and ability a fair and accurate translation of the translation

FURTHER AFFIANT SAYETH NOT.

BEFORE me, the undersigned Notary Public, appeared today, who having first been placed under oath, under his oath stated that he is the person whose signature appears affixed to the foregoing statement and further stated under his oath that what said statement contains is of his personal knowledge and true and correct.

SUBSCRIBED before me on this 16th day of January 2012.

Notary Public in and for the State of New York

My Commission expires:

ROBERT W DENOIA NOTARY PUBLIC-STATE OF NEW YORK No. 01DE5053956 Qualified in New York County My Commission Expires April 18, 2014

AMSTERDAM ALLANTA AUSTIN BARCELONA BER' IN BOGGTA BOSTON BRUSSELS CHARLOTTE CHICAGO CLEVELAND

COLUMBUS DALL -S DENVER DUBAL DUBLIN DUSSELDORF FRANKFURT JENEVA HONG KONG

HOUSTON LONDON LON ANGELES LYON MEXICO CITY MIAM MILAN MININEAROUS 10(11/41/11 MUNICH

MEW OUR PARIS PHILADELPHIA PHOENIX PORTLAND PRACUL RESEARCH RIAL:GLE PARK SAN DIEGO

SAN TRANSISCO

SAN JOSE SEATTLE

SEOUL SINGAPOPE STOCKHOLM STUTTGART SYDNEY

TEL AVIV TOKYO TORONTO VANCOUVER

WASHINGTON DC **ZURICH**